

Peugeot Partner

Tested Model: Citroën Berlingo 1.6 diesel 'Confort', LHD













ADULT OCCUPANT







CHILD OCCUPANT

Ti

PEDESTRIAN

λN

SAFETY ASSIST

DETAILS OF TESTED CAR

SPECIFICATIONS

Tested model	Tested Model: Citroën Berlingo 1.6 diesel 'Confort', LHD
Body type	5 door hatchback
Year of publication	2014
Kerb weight	1431kg
VIN from which rating applies	from VF37J9HP0EJ725408

SAFETY EQUIPMENT

Frontal airbags	Driver (Single Stage), Passenger (Single Stage)
Pre-tensioners	Driver (single), Passenger (single)
Load-limiters	Driver, Passenger
Knee airbags	None
Side airbags	None
Front head restraints	Passive
Passenger airbag switch	Manual switch
ISOFIX anchorages	Rear outboard seats
Integrated child restraint	None
Active Pedestrian Protection	None,
Seatbelt Reminder	Driver, Passenger
Electronic Stability Control	ESP Bosch 8.1, Standard, Manual Switch
Speed Assistance Systems	Driver-set speed limitation, Optional (meeting fitment requirements)
Lane Support	Not available
Autonomous Braking	None, Not Available

Safety equipment is standard across the model range unless stated otherwise



ADULT OCCUPANT

Total 21 pts | 56%

CRASH TEST PERFORMANCE







SIDE	CAR

8 pts

SIDE POLE

0 pts





Side car

Side pole

FRONT OFFSET

HEAD	
Driver airbag contact	stable
Passenger airbag contact	stable
CHEST	
Passenger compartment	stable
Windscreen Pillar rearward	5mm
Steering wheel rearward	none
Steering wheel upward	28mm
Chest contact with steering wheel	none

UPPER LEGS, KNEES AND PELVIS

Stiff structures in dashboard	Steering column and lock; end of facia
Concentrated loads on knees	Steering column and lock; end of facia

LOWER LEGS AND FEET

Footwell Collapse	none
Rearward pedal movement	Clutch - 48mm
Upward pedal movement	Clutch - 3mm

SIDE

Head protection airbag	No
Chest protection airbag	No

WHIPLASH PROTECTION

FRONT, REAR SEATS



Front seats



1,8 pts

Rear seats

HEAD RESTRAINT

Seat description	Standard cloth, 4 way manual
Head restraint type	Passive
Front geometric assessment	0,3 pts
TESTS	
- High severity	1,8 pts
- Medium severity	1,5 pts
- Low severity	1,9 pts

0 pts

AEB CITY

System name Not applicable Fitment Not available













CHILD OCCUPANT

Total 36 pts | 74%

CRASH TEST PERFORMANCE

18 MONTH OLD CHILD

Restraint Römer BabySafe
Facing rearward facing
Installation Adult seatbelt



PERFORMANCE

12 pts

FRONTAL IMPACT

Head forward movement	protected
Head acceleration	good
Chest load	good

SIDE IMPACT

Head containment	protected
Head acceleration	good

3 YEAR OLD CHILD

Restraint Römer Duo Plus Facing forward facing

Installation ISOFIX and TopTether



PERFORMANCE 9,4 pts

FRONTAL IMPACT

Head forward movement	protected
Head acceleration	good
Chest load	fair

SIDE IMPACT

Head containment	protected
Head acceleration	good

CHILD SAFETY FEATURES AND CRS INSTALLATION CHECK





Isofix

Safety features score

Installation check score	12 pts
Pass	Install without problem
Partial Fail	Install with care
Fail	Safety critical problem
Exempt	Installation not allowed

3 pts

		SEAT POSITION							
	FRO	FRONT		2nd ROW			3rd ROW		
	CENTER	RIGHT	LEFT	CENTER	RIGHT	LEFT	CENTER	RIGHT	
Maxi Cosi Cabriofix (Seatbelt)	N/A	Pass	Pass	Pass	Pass	Pass	N/A	Pass	
Römer King Plus (Seatbelt)	N/A	Pass	Pass	Pass	Pass	Pass	N/A	Pass	
Römer Duo Plus (ISOFIX)	N/A	Exempt	Pass	Exempt	Pass	Exempt	N/A	Exempt	
Römer KidFix (Seatbelt)	N/A	Pass	Pass	Pass	Pass	Pass	N/A	Pass	
Maxi Cosi Cabriofix and EasyFix (Seatbelt)	N/A	Pass	Exempt	Pass	Exempt	Exempt	N/A	Exempt	
Maxi Cosi Cabriofix and EasyFix (ISOFIX)	N/A	Exempt	Exempt	Exempt	Exempt	Exempt	N/A	Exempt	
BeSafe iZi Kid X3 ISOfix (ISOFIX)	N/A	Exempt	Exempt	Exempt	Exempt	Exempt	N/A	Exempt	
Maxi Cosi Pearl and Familyfix (ISOFIX)	N/A	Exempt	Exempt	Exempt	Exempt	Exempt	N/A	Exempt	
Römer KidFix (ISOFIX)	N/A	Exempt	Pass	Exempt	Pass	Exempt	N/A	Exempt	
Römer BabySafe (Seatbelt)	N/A	Pass	Pass	Pass	Pass	Pass	N/A	Pass	
Römer Duo Plus (ISOFIX)	N/A	Exempt	Pass	Exempt	Pass	Exempt	N/A	Exempt	



SAFETY ASSIST Total 6 pts | 48%

SPEED ASSISTANCE SYSTEM	1,3 pts
-------------------------	---------

Optional (meeting fitment requirements)

Speed Information Not applicable

Speed Assistance (Manual) Pass

ELECTRONIC STABILITY CONTROL (ESC) 3 pts


- ESP Bosch 8.1 Meets requirements

SEATBELT REMINDER	2 pts
- driver and passenger	Pass
- rear	Not applicable
LANE SUPPORT SYSTEMS	0 pts
Not available	

0



PEDESTRIAN Total 23 pts | 63%



COMMENTS

Peugeot have demonstrated that the Partner is identical to the Citroën Berlingo in every way that will influence safety. Therefore, the star rating of the Peugeot Partner is the same as that of the Berlingo and the results of that vehicle are given in this assessment.

Adult occupant

The passenger compartment remained stable in the frontal impact. Dummy readings indicated good protection of the knees and femurs of the driver and passenger. However, the steering column and its lock, and the end of the facia were posed a risk of injury to occupants of different sizes and to those sat in different positions and the score was penalised. The vehicle scored maximum points in the side barrier test, with good protection of all body regions. A side impact thorax airbag and a head-protecting curtain airbag are both available as an option but were not fitted to the test vehicle. As the curtain airbag is not standard equipment a pole test was not performed. Protection against whiplash injury in a rear-end collision was rated as marginal for both the front and rear seats.

Child occupant

Based on dummy readings in the crash tests, the car scored maximum points for its protection of the 1½ year dummy. Forward movment of the head of the 3 year dummy, sat in a forward-facing restraint, was not excessive but forces in the neck were high and chest acceleration indicated only fair protection of this body region. The passenger airbag can be disabled to allow a rearward-facing restraint to be used in that seating position. However, the markings for the switch are not sufficiently clear and the system was not rewarded. All of the restraint types for which the vehicle is designed could be properly installed and accommodated.

Pedestrian

The bumper provided good protection to pedestrians' legs and scored maximum points. The performance of the front edge of the bonnet was more mixed: good in some areas but weak or poor in others. The bonnet surface provided mostly good protection to the head of a struck pedestrian but poor results were recorded at the bonnet edges and on the stiff windscreen pillars.

Safety assist

Electronic stability control is standard equipment. Early vehicles had a seatbelt reminder for the driver's seat only. From VIN VF37J9HP0EJ725408, the system covers both the driver and front passenger seats. A driver-set speed limitation deviceis available as an option and met Euro NCAP's requirements. The Berlingo does not have an autonomous braking system or lane support.